

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Adequate		
Corrective Action:		Date:	_____

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds.		
Corrective Action:	Location is within a designated setback location, remove Weeds per Rule 603 f. Corrective Action Date 8/27/2020. See attached photos #.1, 2, 3 & 4	Date:	07/27/2020

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment: _____

Multiple Spills and Releases?

Equipment:

Type:			corrective date
Vertical Heater Treater	# 1		
Comment:			
Corrective Action:		Date:	
Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Plunger Lift	# 1		

Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	FIBERGLASS AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Shares berm with crude tanks.				
Corrective Action:					
Date:					
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		39.984515,-104.500284
Comment:	Stained soil (under load off line on crude tank).				
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Corrective action date 8/3/2020. See attached photos #.6				
Date:	08/03/2020				

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
Date:				

Venting:

Yes/No	NO
Comment:	
Corrective Action:	
Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 202396 Type: WELL API Number: 001-07801 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

BradenHead

Comment:

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On July 8, 2020 at approximately 9:17am, I, Inspector Chane Finkenbinder, Conducted an on-site inspection at Shively #21-12, Painted Pegasus Petroleum at API # 001-07801 in Adams County Colorado. While there, I observed a Shut in well. During this inspection the following possible compliance issues were observed: Stained soil (under load off line on crude tank). Control and contain spills/releases and clean up per Rule 906.a. Corrective action date 8/3/2020. See attached photos #.6 Weeds. Location is within a designated setback location, remove Weeds per Rule 603 f. Corrective Action Date 8/27/2020. See attached photos #.1, 2, 3 & 4 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	finkenbc	07/15/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402444365	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5197211
700900225	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5197209