


Inspection Photos
Operator Name: TEP Rocky Mountain LLC
Location: 314289



Entrance sign



Stormwater BMP's installed

Inspection Photos
Operator Name: TEP Rocky Mountain LLC
Location: 314289



2" flowline in excavation ditch



Flowline removed from excavation ditch

Inspection Photos
Operator Name: TEP Rocky Mountain LLC
Location: 314289



2" removed risers



Flowlines removed from excavation

Inspection Photos
Operator Name: TEP Rocky Mountain LLC
Location: 314289



2" flowline cut on edge of location, Flowline is Williams midstream, Flowline will need to capped or plugged