

Issue Report



70 Ranch 10 West 454560

Report created on July 21, 2020

Captured: July 16, 2020

Type	Count
Other	10


No.	Summary	Type	Created	Status
10	Appears to be leaking hammer unions at hi/low valves on various separators.	Other	Jul 20, 2020 at 2:39pm	Open
9	Unused equipment/trash	Other	Jul 20, 2020 at 2:36pm	Open
8	Stained soil around wellheads	Other	Jul 20, 2020 at 2:34pm	Open
7	Oily waste on top of production tanks	Other	Jul 20, 2020 at 2:30pm	Open
6	Oily waste on top of production tanks	Other	Jul 20, 2020 at 2:30pm	Open
5	Stained Soil	Other	Jul 20, 2020 at 2:20pm	Open
4	Unused equipment	Other	Jul 20, 2020 at 2:19pm	Open
3	Inadequate wildlife protection (bird protector) is broken or missing on top of ECD	Other	Jul 20, 2020 at 2:18pm	Open
2	Inadequate wildlife protections (netting) of secondary containments.	Other	Jul 20, 2020 at 2:15pm	Open
1	Inadequate wildlife protection (netting) of secondary containments.	Other	Jul 20, 2020 at 2:14pm	Open

Other



No.	Summary	Created	Status
10	Appears to be leaking hammer unions at hi/low valves on various separator s.	Jul 20, 2020 at 2:39 PM	Open
9	Unused equipment/trash	Jul 20, 2020 at 2:36 PM	Open
8	Stained soil around wellheads	Jul 20, 2020 at 2:34 PM	Open
7	Oily waste on top of production tanks	Jul 20, 2020 at 2:30 PM	Open

6	Oily waste on top of production tanks	Jul 20, 2020 at 2:30 PM	Open
5	Stained Soil	Jul 20, 2020 at 2:20 PM	Open
4	Unused equipment	Jul 20, 2020 at 2:19 PM	Open
3	Inadequate wildlife protection (bird protector) is broken or missing on top of ECD	Jul 20, 2020 at 2:18 PM	Open
2	Inadequate wildlife protections (netting) of secondary containments.	Jul 20, 2020 at 2:15 PM	Open
1	Inadequate wildlife protection (netting) of secondary containments.	Jul 20, 2020 at 2:14 PM	Open

No. 1 OPEN***Captured:*** Jul 16, 2020 at 8:57am**Type**

Other

Lat/Long

40.33405, -104.42986

Summary

Inadequate wildlife protection (netting) of secondary containments.

Created

Jul 20, 2020 at 2:14pm by Adam Kraich

No. 2 OPEN***Captured:*** Jul 16, 2020 at 8:57am**Type**

Other

Lat/Long


40.33405, -104.42986

Summary

Inadequate wildlife protections (netting) of secondary containments.

Created

Jul 20, 2020 at 2:15pm by Adam Kraich

No. 3 OPEN***Captured:*** Jul 16, 2020 at 8:57am**Type**

Other

Lat/Long

40.33380, -104.43129

Summary

Inadequate wildlife protection (bird protector) is broken or missing on top of ECD

Created

Jul 20, 2020 at 2:18pm by Adam Kraich

No. 4 OPEN

Captured: Jul 16, 2020 at 8:57am



Type

Other

Lat/Long

40.33369, -104.43107

Summary

Unused equipment

Created

Jul 20, 2020 at 2:19pm by Adam Kraich

No. 5 OPEN***Captured:*** Jul 16, 2020 at 8:57am**Type**

Other

Lat/Long


40.33419, -104.43124

Summary

Stained Soil

Created

Jul 20, 2020 at 2:20pm by Adam Kraich

No. 6 OPEN***Captured:*** Jul 16, 2020 at 8:57am**Type**

Other

Lat/Long


40.33441, -104.43168

Summary

Oily waste on top of production tanks

Created

Jul 20, 2020 at 2:30pm by Adam Kraich

No. 7 OPEN***Captured:*** Jul 16, 2020 at 8:57am**Type**

Other

Lat/Long

40.33441, -104.43168

Summary

Oily waste on top of production tanks

Created

Jul 20, 2020 at 2:30pm by Adam Kraich

No. 8 OPEN***Captured:*** Jul 16, 2020 at 8:57am**Type**

Other

Lat/Long


40.33478, -104.42946

Summary

Stained soil around wellheads

Created

Jul 20, 2020 at 2:34pm by Adam Kraich

No. 9 OPEN***Captured:*** Jul 16, 2020 at 8:57am**Type**

Other

Lat/Long

40.33362, -104.43029

Summary

Unused equipment/trash

Created

Jul 20, 2020 at 2:36pm by Adam Kraich

No. 10 OPEN***Captured: Jul 16, 2020 at 8:57am*****Type**

Other

Lat/Long

40.33454, -104.43105

Summary

Appears to be leaking hammer unions at hi/low valves on various separators.

Created

Jul 20, 2020 at 2:39pm by Adam Kraich