

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/22/2020

Submitted Date:

07/22/2020

Document Number:

696302165

FIELD INSPECTION FORM

Loc ID 444387 Inspector Name: PETRIE, ERICA On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 96155
Name of Operator: WHITING OIL & GAS CORPORATION
Address: 1700 LINCOLN STREET SUITE 4700
City: DENVER State: CO Zip: 80290

Findings:

- 12 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		WhitingEasternCO@Whiting.com	Eastern Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
444378	WELL	PR	10/01/2017	OW	123-42594	Razor 25M-2434	PR
444379	WELL	PR	10/01/2017	OW	123-42595	Razor 25M-2436	PR
444380	WELL	PR	10/01/2017	OW	123-42596	Razor 25M-2403	PR
444381	WELL	PR	10/01/2017	OW	123-42597	Razor 25M-2404	PR
444382	WELL	PR	10/01/2017	LO	123-42598	Razor 25M-2402	PR
444383	WELL	PR	10/01/2017	OW	123-42599	Razor 25M-2401	PR

General Comment:

Location

Overall Good:

Signs/Marker:

	Type WELLHEAD		
	Comment: 25M-2403 & 2401 Missing Wellhead Signs, see photos		
	Corrective Action: Comply with Rule 210.b.	Date: 08/28/2020	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type LOCATION

Comment: Barbed Wire

Corrective Action:

Date:

Equipment:

corrective date

Type: Plunger Lift	# 6				
Comment:					
Corrective Action:					Date:
Type: Gas Meter Run	# 6				
Comment:	Gas Lift Meters				
Corrective Action:					Date:
Type: Bradenhead	# 6				
Comment:	Appear to be plumbed to surface				
Corrective Action:					Date:

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	444378	Type:	WELL	API Number:	123-42594	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	444379	Type:	WELL	API Number:	123-42595	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	444380	Type:	WELL	API Number:	123-42596	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	444381	Type:	WELL	API Number:	123-42597	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	444382	Type:	WELL	API Number:	123-42598	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	444383	Type:	WELL	API Number:	123-42599	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Routine Field Inspection. 25M-2401 & 2403 are missing Wellhead Signage	petrie	07/22/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696302166	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5205349