

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/22/2020

Submitted Date:

07/22/2020

Document Number:

699801486**FIELD INSPECTION FORM**Loc ID 321999 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10515

Name of Operator: GUNNISON ENERGY LLC

Address: 1801 BROADWAY #1150

City: DENVER State: CO Zip: 80202

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

7 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Gunnison		dan.mcwilliams@oxbow.com	
, Gunnison		jessicadonahue@summiteng.net	
, Engineering		dnr_cogccengineering@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
272542	WELL	SI	09/01/2005	GW	029-06087	SPAULDING PEAK 1294 23-33	TA

**General Comment:****COGCC Inspection Report Summary**

On Wednesday 7/22/20 at approximately 11:30 hours, I, Inspector Corey De Paolo, Conducted an on-site inspection at GUNNISON ENERGY LLC SPAULDING PEAK 1294-612S94W /23NWSE, Location #321999 in Delta County Colorado.

During this inspection the following possible compliance issues were observed: Multiple places with unused equipment. See photo #1578 and #1579 with a corrective action date of 10/22/20. Last MIT performed 7/7/16. No current form 4 requesting temporarily abandoned status. With a corrective action date of 8/22/20.

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location				
<b>Lease Road:</b>				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	1-970-874-7697			
Corrective Action:				Date: _____
<b>Good Housekeeping:</b>				
Type	UNUSED EQUIPMENT			
Comment:	Multiple places with unused equipment. See photo #1578 and #1579			
Corrective Action:	Production facilities, shall be kept free of equipment and supplies not necessary for use on that lease. Remove all unused equipment from location.			Date: 10/22/2020
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	LOCATION			
Comment:	Barbed wire fence around location			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	Hog panels			
Corrective Action:				Date:
<b>Equipment:</b>				
Type: Horizontal Heated Separator	# 2			corrective date
Comment:				
Corrective Action:				Date:
Type: Plunger Lift	# 2			
Comment:				
Corrective Action:				Date:
Type: Bird Protectors	# 1			
Comment:				

Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 1		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 272542 Type: WELL API Number: 029-06087 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: Last MIT preformed 7/7/16. No current form 4 requesting temporarily abandoned status.Corrective Action: A Sundry Notice, Form 4, or other form approved by the Director, shall be submitted annually stating the method the well is closed to the atmosphere and plans for future operation. submit form 4.Date: 08/22/2020

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					
		Berms	Pass			
		Culverts	Pass			
Ditches	Pass					
		Ditches	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<a href="#">No tank battery on location</a>	depaoloc	07/22/2020

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699801487	Photos for Insp. #699801486	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5205391">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5205391</a>