

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/22/2020

Submitted Date:

07/22/2020

Document Number:

700701164

FIELD INSPECTION FORM

Loc ID: 322419 Inspector Name: Ramsey, Scott On-Site Inspection: 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
 13 Number of Comments
 6 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 OGCC Operator Number: 53255
 Name of Operator: MARALEX RESOURCES INC
 Address: P O BOX 338
 City: IGNACIO State: CO Zip: 81137

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, BLM		jbyers@blm.gov	
, Maralex		maralexjr@gmail.com	
, COGCC		dnr_cogccengineering@state.co.us	engineering
, Maralex	970-712-0099	mrinc20@maralexinc.com	all inspections
, COGCC		g.richard.murray@state.co.us	FLOW LINES
, COGCC		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210457	WELL	SI	09/01/2017	GW	045-06213	FEDERAL 26-3	SI

General Comment:

COGCC Inspection Report Summary
 On Wednesday 7/22/20 at approximately 9:30 AM, I, Inspector Scott Ramsey, conducted a High risk list/follow up inspection at Maralex Federal # 26-3, at Location # 322419 in Garfield county Colorado.
 While there, I observed well is shut in. Braden head is attached to tank and open. Corrective actions from previous inspection document # 68930226 have not been addressed.
 During this inspection the following possible compliance issues were observed:

- Well head is missing signage
- Battery signage is missing information
- Uncontrolled weeds in tank battery
- Debris
- MIT is past due last MIT was done 11/10/2014
- Unused equipment
- Last calibration was done 7/23/2015
- Unmarked dead man

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Sign not posted at wellhead Missing information at Battery sign		
Corrective Action:	Install sign to comply with Rule 210.b.		Date: 10/26/2018
Emergency Contact Number:			
Comment:	970-858-8550		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	DEBRIS		
Comment:	debris around well head and in tank containment		
Corrective Action:	remove debris		Date: 08/19/2020
Type	OTHER		
Comment:	unmarked dead man		
Corrective Action:	mark dead men clearly or remove		Date: 08/19/2020
Type	WEEDS		
Comment:	Uncontrolled weeds in battery containment		
Corrective Action:	Comply with Rule 603.f .		Date: 10/08/2018
Type	UNUSED EQUIPMENT		
Comment:	unused equipment unmarked flow line		
Corrective Action:	Comply with Rule 603.f . For unused , unmarked flowline risers 24 hrs to lock out tag out. 30 days to remove riser.		Date: 10/28/2018
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	TANK BATTERY		
Comment:			
Corrective Action:			Date:

Equipment:			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Last meter calibration was done 7/23/2015		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	YES	
Comment:	braden head is open to tank	
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 210457 Type: WELL API Number: 045-06213 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: MIT DOC# 1726803 was done on 11/10/2014. MIT is past due. Well head is locked out and tagged out.
No Form 4 on file for continued TA status.

Corrective Action: A Sundry Notice, Form 4, shall be submitted annually stating the method the well is closed to the atmosphere and plans for future operation. MIT Needs to be done. A mechanical integrity test shall be performed on each temporarily abandoned well on five year intervals from the date of the initial mechanical integrity test was performed, as long as the well remained temporarily abandoned.

Date: 10/28/2018

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches		Ditches				
		Culverts				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700701166	Photos for Federal #26-3	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5205424