

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/14/2020

Submitted Date:

07/15/2020

Document Number:

697601017**FIELD INSPECTION FORM**Loc ID 331731 Inspector Name: GINTAUTAS, PETER On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Hamilton, Greg		Gregory_Hamilton@oxy.com	
, Anadarko		COGCCinspections@Anadarko.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
265232	WELL	SI	04/01/2019	OW	123-21202	DECHANT 9-19A	SI
476967	TANK BATTERY	AC	07/14/2020		-	Dechant NESE 19 battery	EI

**General Comment:**

production facilities at battery 476967 are not co-located with related well and its location.  
well not inspected in this report  
remediation 13362 open for more than 12 months with removal of PBV used to store produced water as objective of approved site investigation and remediation plan

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: [emergency contact information on battery sign as shown in attached photo](#)Corrective Action:  Date: Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: [no spills observed at surface](#)☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		

Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV FIBERGLASS		,
Comment:	site investigation and remediation project 13262 approved more than 12 months ago for removal of PBV at this facility with no update as to progress or change of plans received by COGCC				
Corrective Action:	Please check as to whether removal is still planned or if plans to remove have changed.  If removal is now not to be done please request closure. If removal is still planned please submit updated form 27 with current planned date of removal				Date: 08/14/2020

**Paint**

Condition	
Other (Content)	
Other (Capacity)	75 bbls
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient		Adequate	
Comment:	in same berm system as crude tank				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		40.122143,-104.697535
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient		Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	
Comment:	
Corrective Action:	Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	265232	Type:	WELL	API Number:	123-21202	Status:	SI	Insp. Status:	SI
Facility ID:	476967	Type:	TANK	API Number:	-	Status:	AC	Insp. Status:	EI

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402444364	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5197210">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5197210</a>
697601017	INSPECTION APPROVED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5201110">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5201110</a>
697601018	battery sign	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5197206">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5197206</a>
697601019	partly buried produced water vessel	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5197207">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5197207</a>
697601020	separator and ECD	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5197208">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5197208</a>