



**Location**

Overall Good:

**Signs/Marker:**

|                    |              |  |       |
|--------------------|--------------|--|-------|
| Type               | WELLHEAD     |  |       |
| Comment:           | adequate x 3 |  |       |
| Corrective Action: |              |  | Date: |

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

**Spills:**

| Type | Area | Volume |  |
|------|------|--------|--|
|------|------|--------|--|

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

|                    |                                     |  |       |
|--------------------|-------------------------------------|--|-------|
| Type               | WELLHEAD                            |  |       |
| Comment:           | wrought iron                        |  |       |
| Corrective Action: |                                     |  | Date: |
| Type               | OTHER                               |  |       |
| Comment:           | transformers- fabricated steel pipe |  |       |
| Corrective Action: |                                     |  | Date: |
| Type               | PUMP JACK                           |  |       |
| Comment:           | hog fence                           |  |       |
| Corrective Action: |                                     |  | Date: |

**Equipment:**

|                           |  |  |                 |
|---------------------------|--|--|-----------------|
| Type: Prime Mover         | # 1  |  | corrective date |
| Comment:                  | electric motor   |  |                 |
| Corrective Action:        |  |  | Date:           |
| Type: Bradenhead          | # 3  |  |                 |
| Comment:                  | Kerr McGee wells partially exposed at surface, KP Kauffman appears to be plumbed to cellar surface |  |                 |
| Corrective Action:        |  |  | Date:           |
| Type: Pump Jack           | # 1  |  |                 |
| Comment:                  |  |  |                 |
| Corrective Action:        |  |  | Date:           |
| Type: Ancillary equipment | # 1  |  |                 |
| Comment:                  | electric panel, meter box and transformers   |  |                 |
| Corrective Action:        |  |  | Date:           |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Inspected Facilities**

Facility ID: 292472 Type: WELL API Number: 123-26364 Status: TA Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: TA since 12-23-2019 Form 04 (TA) Doc # 402374817 submitted on 4-19-2020 and is approved.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 293181 Type: WELL API Number: 123-26490 Status: TA Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: TA since 12-24-2019 Form 04 (TA) Doc # 402374819 submitted on 4-19-2020 and is approved

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

| Comment   | User   | Date       |
|---|--------|------------|
| <p>COGCC Inspection Report Summary<br/>                     On Thursday 7/23/2020 at approximately 1135 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a Kerr McGee location:<br/>                     Dacono State 22-36 at API #05-123-26364 in Weld County Colorado.<br/>                     While there, I observed multi-well pad. Dacono State 22-36: TA since 12-23-2019 Form 04 (TA) Doc # 402374817 submitted on 4-19-2020 and is approved. Dacono State 6-36: TA since 12-24-2019 Form 04 (TA) Doc # 402374819 submitted on 4-19-2020 and is approved.<br/>                     During this inspection no compliance issues were observed:<br/>                     See attached photos.<br/>                     Location is dry, weather is clear.<br/>                     No follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.<br/>                     Continuing education COGCC Inspection Report Summary.<br/>                     This is a summary of inspection report.</p> | revasr | 07/23/2020 |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description         | URL   |
|--------------|---------------------|---|
| 699302186    | INSPECTION APPROVED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5203147">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5203147</a> |
| 699302187    | location pics       | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5203135">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5203135</a> |