

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/21/2020

Submitted Date:

07/22/2020

Document Number:

699601468

**FIELD INSPECTION FORM**

Loc ID: 303554    Inspector Name: SCHURE, KYM    On-Site Inspection:     2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10699  
Name of Operator: OWN RESOURCES OPERATING LLC  
Address: 38 PALMER CREST CT  
City: SPRING    State: TX    Zip: 77381

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

11 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Dolezal, Pat		pat.dolezal@ownresources.com	<a href="#">Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
253281	WELL	PR	12/30/1999	GW	125-07158	W. KORF 3	PR

**General Comment:**

[Routine Site Inspection FIR - SATISFACTORY](#)

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Cropland w/seasonal access		
Corrective ActionL		Date:	
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Satisfactory		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Satisfactory		Date: _____
Corrective Action:			
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:	NA		
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Steel pipe		
Corrective Action:		Date:	
<b>Equipment:</b>			
Type: Gas Meter Run	# 1		corrective date
Comment:	Meter shows calibration within (1) yr. of FIR		
Corrective Action:		Date:	
Type: Other	# 0		
Comment:	No change in equipment inventoried		
Corrective Action:		Date:	
<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 253281 Type: WELL API Number: 125-07158 Status: PR Insp. Status: PR

**Producing Well**

Comment: [FGW](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	In Process	Other	In Process			

Comment: Located within cropland with rotational tillage

Corrective Action:

Date:

**Pits:**  NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<a href="#">Routine FIR</a>	schureky	07/22/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699601468	INSPECTION APPROVED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5202181">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5202181</a>
699601469	MR - Certificate	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5202094">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5202094</a>