

## Inspection Photos

Location Name: MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W/23SWNW

Location ID: 312610



Network: Jul 14, 2020 at 12:34:56 PM MD  
Local: Jul 14, 2020 at 12:34:56 PM MD



Network: Apr 7, 2020 at 11:33:37 AM MD  
Local: Apr 7, 2020 at 11:33:37 AM MD  
+39.3452, -108.303

**Photo #1515 from entrance to location**

**Photo #0921 from inspection #699800864 inspection conducted on 4/7/20.**

## Inspection Photos

Location Name: MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W/23SWNW

Location ID: 312610



Network: Jul 14, 2020 at 12:35:18 PM MDT  
Local: Jul 14, 2020 at 12:35:18 PM MDT



Network: Apr 7, 2020 at 11:32:39 AM MDT  
Local: Apr 7, 2020 at 11:32:39 AM MDT  
+39.3451,-108.303

**Photo #1516 from Tank NFPA label weathered and not legible.**

**Photo #0920 from inspection #699800864 inspection conducted on 4/7/20.**

## Inspection Photos

Location Name: MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W/23SWNW

Location ID: 312610



**Photo #1517 Multiple places with unused equipment on location.**



**Photo #0918 from inspection #699800864 inspection conducted on 4/7/20.**

## Inspection Photos

Location Name: MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W/23SWNW

Location ID: 312610



Photo #1520 Debris on location.



Photo #0922 from inspection #699800864 inspection conducted on 4/7/20.

## Inspection Photos

Location Name: MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W/23SWNW

Location ID: 312610



**Photo #1518 Unmarked deadman.**