

Inspection Photos

7/14/2020

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 425805

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 425805



Photo 1: Photo taken from the west end of the Location, facing north. Photos 1-4 provide an overview of the Location from north, northeast, southeast to south. Photo shows interim reclamation activities of the Location are in process.



Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 425805



Photo 3: See comments under photo 1.



Photo 4: See comments under photo 1.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 425805



Photo 5: Photo taken from the northwest end of the Location, facing west. Photo shows unused pipe equipment stored on the Location.



Photo 6: Photo taken from the northwest end of the Location. Photo shows Musk thistle plant. This is a Colorado State listed noxious weed.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 425805



Photo 7: Photo taken from the north end of the Location facing south. Photo shows interim reclamation of the Location is in process.



Photo 8: Photo taken from the south end of the Location facing north. Photo shows interim reclamation of the Location is in process.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 425805



Photo 9: Photo is example of several wells on the Location missing signage.



Photo 10: Photo is example of several wells on the Location observed with missing signage.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 425805



Photo 11: Photo taken from the access road, west of the Location facing north. Photo shows Operator implemented straw wattles along perimeter of the Location. Photo shows BMP has not been installed in accordance with good engineering practices and is not in proper functioning condition.



Photo 12: Photo taken from the access road, west of the Location facing north. Photo shows Operator implemented straw wattles along perimeter of the Location. Photo shows BMP has not been installed in accordance with good engineering practices and is not in proper functioning condition; Wattles require trenching and backfilling.