



**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Adequate		
Corrective Action:		Date:	

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Barbwire		
Corrective Action:		Date:	

**Equipment:**

Equipment	#		corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface.		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 272117 Type: WELL API Number: 123-22180 Status: SI Insp. Status: SI**Idle Well**Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_Comment: Corrective Action:  Date: \_\_\_\_\_**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary  On Wednesday 7/22/20 at approximately 0750hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Donovan D 2-4JI of Noble Energy at Location ID: 332347 in Weld County, Colorado.  While there, I observed a production well that is SI, LO/TO.  No violation of the COGCC rules were observed at the time of inspection.  This is a summary of inspection report.  Continuing education inspections</p>	burnsa	07/22/2020

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699102111	INSPECTION APPROVED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5207236">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5207236</a>
699102112	Inspection Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5208102">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5208102</a>