

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/14/2020

Submitted Date:

07/14/2020

Document Number:

699801438

FIELD INSPECTION FORM

Loc ID 312601 Inspector Name: De Paolo, Corey On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
9 Number of Comments
4 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 OGCC Operator Number: 53255
 Name of Operator: MARALEX RESOURCES INC
 Address: P O BOX 338
 City: IGNACIO State: CO Zip: 81137

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, BLM		jbyers@blm.gov	
Kellerby, Shaun		shaun.kellerby@state.co.us	
Graves, Jim		mrinc20@maralexinc.com	
Pesicka, Conor		conor.pesicka@state.co.us	
Jordan, Reid		maralextechjr@gmail.com	
, Engineering		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221999	WELL	SI	05/01/2010	GW	077-08601	SOUTH SHALE RIDGE 4-13	SI

General Comment:

[COGCC Inspection Report Summary](#)
 On Tuesday 7/14/20 at approximately 13:30 hours, I, Inspector Corey De Paolo, Conducted a follow up inspection at MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W /13NWNW, Location #312601 in Mesa County Colorado.
 Refer to document #699800920 inspection conducted on 4/15/20. Not all previous corrective actions have been completed. While there, I observed normal production operations.
 During this inspection the following possible compliance issues were observed: No battery sign on location. With a corrective action date of 10/14/20. Tank capacity not labeled. See photo #0979 and #1522 with a previous corrective action date of 6/15/20. Multiple places with debris on location. See photo #0980, #1524, #0981 and #1523 with a previous corrective action date of 4/22/20. MIT required on well. With a previous corrective action date of 5/15/20.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.
 This is a summary of inspection report.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Tank capacity not labeled. See photo #0979 and #1522		
Corrective Action:	All tanks with a capacity of ten (10) barrels or greater shall be label with tank capacity. Properly label tank.		Date: 06/15/2020
Type	BATTERY		
Comment:	No battery sign on location.		
Corrective Action:	Within sixty (60) days after the installation of a battery, a permanent sign shall be located at the battery. Install battery sign.		Date: 10/14/2020
Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Location is being used for a storage facility. BLM Storage ROW SERIAL NUMBER COC-64694 is on record.		
Corrective Action:			Date:
Type	DEBRIS		
Comment:	Multiple places with debris on location. See photo #0980, #1524, #0981 and #1523.		
Corrective Action:	Production facilities, shall be kept free of weeds and rubbish. Remove all debris from location.		Date: 04/22/2020
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Gas Meter Run	# 2		corrective date
Comment:			
Corrective Action:			Date:
Type: Other	#		
Comment:	Stored sucker rod and various piles of stored pipe.		

Corrective Action:		Date:	
Type: Pump Jack	# 5		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 3		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	FIBERGLASS AST		
Comment:	Capacity not labeled				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 221999 Type: WELL API Number: 077-08601 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well last produced April 2010. Last MIT preformed on 2/16/15.

Corrective Action: A mechanical integrity test shall be performed on each shut-in well on 5 year intervals from the date the initial mechanical integrity test was performed. Preform MIT on well.

Date: 07/15/2020

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
		Berms				
Ditches						
		Culverts				
Waddles						
		Ditches				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402444301	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5197115
699801438	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5207379
699801439	Photos for Insp. #699801438	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5208204