

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

07/17/2020

Submitted Date:

07/17/2020

Document Number:

700701135

FIELD INSPECTION FORM

Loc ID 334612	Inspector Name: Ramsey, Scott	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: 10456 Name of Operator: CAERUS PICEANCE LLC Address: 1001 17TH STREET #1600 City: DENVER State: CO Zip: 80202				Findings: 11 Number of Comments 2 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:			
Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
270111	WELL	PR	10/09/2008	GW	045-09455	BENZEL 1-16C (P1W)	PR
270112	WELL	PR	05/30/2004	GW	045-09456	BENZEL 1-16D (P1W)	PR
270179	WELL	PR	10/27/2003	GW	045-09484	SHAEFFER 12-1C (P1W)	PR
270180	WELL	PR	05/31/2004	GW	045-09485	SHAEFFER 12-1D (P1W)	PR
271339	WELL	PR	05/25/2004	GW	045-09867	BENZEL 1-15C	PR
271340	WELL	PR	04/28/2004	GW	045-09868	SHAEFFER 12-2A (P1W)	PR

General Comment: COGCC Inspection Report Summary On Friday 7/17/20 at approximately 10:30 AM, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus P1W, at Location # 334612 in Garfield county Colorado. While there, I observed normal production operations. All meters have been calibrated on location within the past year. During this inspection the following possible compliance issues were observed: • Holes in containment • Debris in containment Refer to photograph of observed compliance issue. A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.
--

Location

Lease Road:

Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☒**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911		
Corrective Action:		Date:	

Good Housekeeping:

Type	DEBRIS		
Comment:	debris in tank battery		
Corrective Action:	remove debris	Date:	08/17/2020

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Plunger Lift	# 6		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 7		
Comment:	All meters calibrated on location within a year.		

Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 5		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Insufficient	Inadequate
Comment:	holes in base of containment see photos			
Corrective Action:	repair secondary containment			Date: 08/17/2020

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities						
Facility ID:	270111	Type:	WELL	API Number: 045-09455	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing					
Corrective Action:						Date:
Facility ID:	270112	Type:	WELL	API Number: 045-09456	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing					
Corrective Action:						Date:
Facility ID:	270179	Type:	WELL	API Number: 045-09484	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing					
Corrective Action:						Date:
Facility ID:	270180	Type:	WELL	API Number: 045-09485	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing					
Corrective Action:						Date:
Facility ID:	271339	Type:	WELL	API Number: 045-09867	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing					
Corrective Action:						Date:
Facility ID:	271340	Type:	WELL	API Number: 045-09868	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing					
Corrective Action:						Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms		Culverts				
Ditches		Ditches				
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402445986	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5199051
700701135	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5207698
700701141	photos for P1W	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5208182