

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/28/2020

Submitted Date:

07/28/2020

Document Number:

699501602**FIELD INSPECTION FORM**Loc ID 434221 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCCinspections@anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
434217	WELL	PR	05/11/2014	OW	123-38030	HOWARD 38C-33HZ	PR
434218	WELL	PR	05/19/2014	OW	123-38031	HOWARD 36N-33HZ	PR
434219	WELL	PR	05/19/2014	OW	123-38032	HOWARD 37N-33HZ	PR
434220	WELL	PR	05/19/2014	OW	123-38033	HOWARD 15C-33HZ	PR
434222	WELL	PR	12/01/2019	OW	123-38034	HOWARD 16N-33HZ	PR
434223	WELL	SI	07/01/2019	OW	123-38035	HOWARD 37C-33HZ	SI

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type WELLHEAD

Comment: Red AG fencing

Corrective Action:

Date:

Equipment:

corrective date

Type: Ancillary equipment

1

Comment: automation

Corrective Action:

Date:

Type: Bradenhead

6

Comment:

Corrective Action:

Date:

Type: Plunger Lift

6

Comment:

Corrective Action:

Date:

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected FacilitiesFacility ID: 434217 Type: WELL API Number: 123-38030 Status: PR Insp. Status: PRFacility ID: 434218 Type: WELL API Number: 123-38031 Status: PR Insp. Status: PRFacility ID: 434219 Type: WELL API Number: 123-38032 Status: PR Insp. Status: PRFacility ID: 434220 Type: WELL API Number: 123-38033 Status: PR Insp. Status: PRFacility ID: 434222 Type: WELL API Number: 123-38034 Status: PR Insp. Status: PRFacility ID: 434223 Type: WELL API Number: 123-38035 Status: SI Insp. Status: SI**Producing Well**Comment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
At time of inspection location appears to be in compliance with COGCC rules. At time of inspection weather conditions were overcast and calm.	medinaj	07/28/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699501603	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5212311