

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/27/2020

Submitted Date:

07/28/2020

Document Number:

696103392

FIELD INSPECTION FORM

Loc ID 305755 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10261
Name of Operator: BAYSWATER EXPLORATION & PRODUCTION LLC
Address: 730 17TH ST STE 500
City: DENVER State: CO Zip: 80202

Findings:

- 9 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		wellinspections@bayswater.us	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
281822	WELL	PA	10/09/2018	OW	123-23440	FOSS 10-23	PA

General Comment:

This is a **PLUGGED & ABANDONED WELL / ABANDONED BATTERY** inspection.
Well(s): 1: Plugged & Abandoned | PA.
Battery: Abandoned. ALL equipment removed.
Abandoned Battery SE corner GPS coordinates: 40.502875, -104.545183

Abandoned Centralized Battery formerly served 4 Location IDs (305755, 305756, 310508, 302776).
(Well(s): 4: Plugged & Abandoned | PA).

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	#	Comment	Corrective Action	Date	corrective date
Type: Gas Meter Run	# 0	Plugged & Abandoned PA. Battery Abandoned. ALL Equipment Removed.			
Type: Emission Control Device	# 0	Plugged & Abandoned PA. Battery Abandoned. ALL Equipment Removed.			
Type: Plunger Lift	# 0	Plugged & Abandoned PA. Battery Abandoned. ALL Equipment Removed.			
Type: Horizontal Heated Separator	# 0	Plugged & Abandoned PA. Battery Abandoned. ALL Equipment Removed.			

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	0				
Comment:	Plugged & Abandoned PA. Battery Abandoned. ALL Equipment Removed.				
Corrective Action:					Date:

Paint

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:						Date:	
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
PRODUCED WATER	0				,		
Comment:		Plugged & Abandoned PA. Battery Abandoned. ALL Equipment Removed.					
Corrective Action:						Date:	

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:		Date:		

Venting:

Yes/No		
Comment:		
Corrective Action:	Date:	

Flaring:

Type		
Comment:		
Corrective Action:	Date:	

Inspected FacilitiesFacility ID: 281822 Type: WELL API Number: 123-23440 Status: PA Insp. Status: PA**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On MON 07/27/2020 at approximately 11:20 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: BAYSWATER EXPLORATION & PRODUCTION LLC Location Name: FOSS-66N64W /10SWNW Location ID: 305755 Well Name: Foss 10-23 API: 05-123-23440 Location County: Weld County, Colorado Weather: Partly cloudy, dry.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Battery: Abandoned. ALL equipment removed. Abandoned Battery SE corner GPS coordinates: 40.502875, -104.545183</p> <p>Abandoned Centralized Battery formerly served 4 Location IDs (305755, 305756, 310508, 302776). (Well(s): 4: Plugged & Abandoned PA).</p> <p>WELL STATUS COMMENT: Plugged & Abandoned PA. Well appears to be cut / capped. Form 6 doc. #401870692 indicates plugging, cut/cap date: 10/09/2018. Approved.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	07/28/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696103393	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5212463