

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

Equipment:		corrective date
Type: Bradenhead	# 2	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 2	
Comment:		
Corrective Action:		Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 431543 Type: WELL API Number: 123-36661 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: TA

Corrective Action: Date:

Facility ID: 431548 Type: WELL API Number: 123-36664 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: TA

Corrective Action: Date:

COGCC Comments

Comment	User	Date
This is a follow up inspection to previous inspection DOC#: 679602552. All previous corrective actions have been resolved. No new corrective actions were observed at the time of re-inspection. **Weather Conditions: cloudy, dry ground	santistb	07/28/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679603134	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5212556