

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/28/2020

Submitted Date:

07/28/2020

Document Number:

689804461**FIELD INSPECTION FORM**Loc ID 313078 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: **Operator Information:**OGCC Operator Number: 10559Name of Operator: SOUTHLAND ROYALTY COMPANY LLCAddress: 400 WEST 7TH STREETCity: FORT WORTH State: TX Zip: 76102**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Gallenbeck, Danny		dgallenbeck@ctfieldsvcs.com	
Elgin, Jerry		jelgin@mspartners.com	
Blaylock, Connie		cblaylock@mspartners.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
223531	WELL	SI	12/22/2011	GW	081-06898	LATIN 33-12	SI

General Comment:

MIT witness.

Inspected FacilitiesFacility ID: 223531 Type: WELL API Number: 081-06898 Status: SI Insp. Status: SI**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: Inspector on location to witness MIT. Form 42 document number 402444115.
 Tubing is known to have holes in it. MIT was performed by transferring pressure from
 tubing to casing and monitoring the surface casing. 630 PSI on tubing and 0 on casing to
 start test. 630 PSI on both to end test.

Corrective Action: _____ Date: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689804462	Inspection Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5212557