

Inspection Photos

API: 055-06214

Operator: PETROGLYPH OPERATING CO INC

Inspection Date: 7/22/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 055-06214 | Date: 7/22/2020

Inspection Photos



Photo 1. Facing northwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06214 | Date: 7/22/2020

Inspection Photos



Photo 2. There is a pile of rock debris that remains along the slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06214 | Date: 7/22/2020

Inspection Photos



Photo 3. The outlet culvert has filled in with sediment and has not been maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06214 | Date: 7/22/2020

Inspection Photos



Photo 4. West side of the location facing north.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06214 | Date: 7/22/2020

Inspection Photos



Photo 5. Facing northeast at the location. There is two plastic pipes that remain shown at red arrows.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06214 | Date: 7/22/2020

Inspection Photos



Photo 6. View of plastic pipe extending out of the ground shown in previous photo.



Photo 7. View of plastic pipe extending out of the ground shown in previous photo.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos



Photo 8. Facing south at the location. The vegetation is progressing throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06214 | Date: 7/22/2020