

Inspection Photos

API: 055-06157

Operator: PETROGLYPH OPERATING

Inspection Date: 7/27/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06157 | Date: 7/27/2020

Inspection Photos



Photo 1. Facing northwest along the former access road. This area of erosion has not been repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06157 | Date: 7/27/2020

Inspection Photos



Photo 2. Facing north toward the location. Vegetation appears to be fully established at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06157 | Date: 7/27/2020

Inspection Photos



Photo 3. Facing south at the location. Vegetation appears to be fully established at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06157 | Date: 7/27/2020

Inspection Photos



Photo 4. The disturbance area which heads northwest appears to be revegetated. This area was not fully inspected further.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06157 | Date: 7/27/2020

Inspection Photos



Photo 5. Facing east toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06157 | Date: 7/27/2020