

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/22/2020

Submitted Date:

07/22/2020

Document Number:

700701165

FIELD INSPECTION FORM

Loc ID: 322369
Inspector Name: Ramsey, Scott
On-Site Inspection:
2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
 13 Number of Comments
 7 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 OGCC Operator Number: 53255
 Name of Operator: MARALEX RESOURCES INC
 Address: P O BOX 338
 City: IGNACIO State: CO Zip: 81137

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, Maralex		maralexjr@gmail.com	
, COGCC		dnr_cogccengineering@state.co.us	engineering
, Maralex	970-712-0099	mrinc20@maralexinc.com	all inspections
, COGCC		g.richard.murray@state.co.us	FLOW LINES
, COGCC		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210371	WELL	SI	09/01/2017	GW	045-06127	RIFLE-BOULTON 1	SI

General Comment:

COGCC Inspection Report Summary
 On Wednesday 7/22/20 at approximately 12:30 PM, I, Inspector Scott Ramsey, conducted a follow up inspection at Maralex Rifle-boulton #1, at Location # 322369 in Garfield county Colorado.
 While there, I observed all C/A(s) from previous inspections document #'S 689302263, 689301993 and 700700518 have not been completed, previous inspections were done 11/05/2018, 9/26/2018 and 4/21/2020. This well is T/A.
 The Braden head is plumbed into the tank and is open to the tank, I could hear the Braden head venting into the tank from approximately 300 foot away. The tank has a pipe on the side that is attached and open to atmosphere.
 During this inspection the following possible compliance issues were observed:
 • Well head sign is missing (C/A date 10/28/2018)
 • Unused, unmarked flow lines (C/A date 10/28/2018)
 • Debris in and around tank battery
 • MIT is not current and there is no form 4 (C/A date for form 4 is 10/28/2018)
 • Secondary containment is not satisfactory
 • Emergency contact does not have 911
 • Casing master valve is actively leaking called operator

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Well head sign missing		
Corrective Action:	Install sign to comply with Rule 210.b.		Date: 10/28/2018
Emergency Contact Number:			
Comment:	970-563-4000/ no evidence of 911		
Corrective Action:	Install sign to reflect EMS		Date: 07/17/2020
Good Housekeeping:			
Type	OTHER		
Comment:	Casing master valve is actively leaking called operator spoke with Jim Graves.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition. If leak is found Immediate call to operator 24 hours to fix the leak or isolate leak.		Date: 07/23/2020
Type	UNUSED EQUIPMENT		
Comment:	Unused, unmarked flowlines.		
Corrective Action:	Comply with Rule 603.f . For unused , unmarked flowline risers 24 hrs to lock out tag out. 30 days to remove riser.		Date: 10/28/2018
Type	DEBRIS		
Comment:	weeds and debris in and around tank battery containment, and Wellhead		
Corrective Action:	Remove all weeds and debris see photos		Date: 05/08/2020
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Equipment:			
Type: Plunger Lift	# 1		corrective date
Comment:	well is T/A		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		

Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	Inadequate berms around tank			
Corrective Action:	Repair or install berms or other secondary containment devices			Date: 06/12/2020

Venting:

Yes/No	YES
Comment:	braden head is venting to tank, it can be heard from a distance. There is a form 17 on file.
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 210371 Type: WELL API Number: 045-06127 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Last MIT document #2493367 was done 10/9/2014 and is over due for another MIT to maintain status, No Form 4 on file for continued TA status.

Corrective Action: A Sundry Notice, Form 4, shall be submitted annually stating the method the well is closed to the atmosphere and plans for future operation. no evidence in well file of T/A status.
A mechanical integrity test shall be performed on each temporarily abandoned well on five year intervals from the date of the initial mechanical integrity test was performed, as long as the well remained temporarily abandoned.

Date: 10/28/2018

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms		Culverts				
		Ditches				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402449258	INSPECTION SUBMITTED	402449258.pdf
402451414	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5206346
700701167	Photos for rifle-boulton #1	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5205426