

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/22/2020

Submitted Date:

07/29/2020

Document Number:

695103003**FIELD INSPECTION FORM**Loc ID 306873 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 1199 MAIN AVENUE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**8 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		SanJuanCOGCC@bp.com	<a href="#">All Inspections</a>
Beebe, Sabre		sabre.beebe@bpx.com	<a href="#">All Inspections</a>
Labowskie, Steve		steve.labowskie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
271492	WELL	PR	08/01/2018	GW	067-08931	LE PLATT B 1	PR

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	WEEDS		
Comment:	PHOTO 5: NOXIOUS WEEDS ON NORTH EDGE OF LOCATION NEAR GAS METER RUN FENCING.		
Corrective Action:	REMOVE NOXIOUS WEEDS COMPLY WITH RULE 1003.f.		Date: 07/29/2020
Type	OTHER		
Comment:	PHOTO 3: Natural gas powered engine exhaust is staining soil/gravel around area of muffler. Remove stained soil/gravel and dispose. PHOTO 4: Approx 2' x 2' area of stained soil/gravel around base of wellhead. Clean-up and dispose of stained soil/gravel per Rule 1102.f.(2) and Rule 907.e.		
Corrective Action:	Comply with Rule 1102.f.(2) for best self inspection, maintenance and housekeeping to prevent breakdown or failure of BMP's. CA DATE IS ORIGINAL FROM PREVIOUS INSPECTION DOC#687904818		Date: 07/29/2020

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	PUMP JACK		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	FENCE AROUND GAS METER RUN		
Corrective Action:			Date:

**Equipment:**

Type: Gas Meter Run	# 1		corrective date
Comment:	CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	IS PLUMBED TO SURFACE		
Corrective Action:			Date:

**Venting:**

Yes/No	NO		
--------	----	--	--

Comment:			
Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

<b>Inspected Facilities</b>				
Facility ID: 271492	Type: WELL	API Number: 067-08931	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:				
Corrective Action:				Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
THIS IS A FOLLOW UP TO INSPECTION DOC# 687904818. THE CA FOR OILY RAGGS HAS BEEN ADDRESSED HOWEVER IT APPEARS THAT THE CA'S FOR IMPACTED SOILS AROUND WELLHEAD AND PUMPJACK MUFFLER HAVE NOT BEEN ADDRESSED. SEE HOUSEKEEPING FOR DETAILS ON THESE CA'S AND AN ADDITIONAL CA.	beardslt	07/22/2020

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695103004	INSPECTION PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5213034">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5213034</a>