

Inspection Photos

Location Name: HUBER-TINKER 1-9


API#: 05-067-07545

INSP. #: 695103018



Colorado Oil & Gas Conservation Commission
37.23022, -107.75637, 2046.0m, 156°
2020/07/23 08:30:52

PHOTO 1: LOCATION



Colorado Oil & Gas Conservation Commission
37.2298, -107.75626, 2054.0m, 198°
2020/07/23 08:33:11

PHOTO 2: WELL SIGN

Inspection Photos

Location Name: HUBER-TINKER 1-9

API#: 05-067-07545

INSP. #: 695103018



PHOTO 3: MATURE FLOWERING NOXIOUS WEEDS (THISLE) AROUND LOCATION ON THE INTERIM RECLAMATION AREA. CONTROL WEEDS (CA DATE REMAINS THE SAME AS PREVIOUS INSPECTION DOC#693901263 5-1-20

PHOTO 4: ANOTHER IMAGE OF MATURE FLOWERING NOXIOUS WEEDS (THISLE) FROM PHOTO 3.

Inspection Photos
Location Name: HUBER-TINKER 1-9
API#: 05-067-07545
INSP. #: 695103018



PHOTO 5: Natural gas powered engine exhaust is impacting soil/gravel around area of muffler.

Remove stained soil/gravel and dispose. Comply with Rule 1102.f.(2) for best self inspection, maintenance and housekeeping to prevent breakdown or failure of BMP's. ca date 10-23-20.



PHOTO 4: Approx 2' x 2' area of stained soil/gravel around base of wellhead. **Clean-up and dispose of stained soil/gravel per Rule 1102.f.(2) and Rule 907.e. ca date 10-23-20.**

Inspection Photos
Location Name: HUBER-TINKER 1-9
API#: 05-067-07545
INSP. #: 695103018



PHOTO 7: CULVERT AT ENTRANCE OF LOCATION IS ALMOST PLUGGED COMPLETELY. CLEAN AND MAINTAIN CULVERT IN ORDER TO PREVENT BREAKDOWN OF BMP'S. Install or repair required BMPs per Rule 1002.f.(2)C. CA DATE 10-23-20



PHOTO 8: AN IMAGE OF THE OTHER SIDE OF CULVERT MENTIONED IN PHOTO 7.

Inspection Photos

Location Name: HUBER-TINKER 1-9

API#: 05-067-07545

INSP. #: 695103018



PHOTO 9: PHOTO OF THE CULVET JUST DOWN GRADE OF CULVERT IN PHOTO 7. FOLLOW CA LISTED ON PHOTO 7.



PHOTO 10: UNUSED EQUIPMENT STORED JUST OVER BERM ON INTERIM RECLAMATION AREA. REMOVE UNUSED EQUIPMENT, COMPLY WITH RULE 603.f. CA DATE 10-23-20.