

Inspection Photos
Location Name: HURT 1-4
API#: 05-067-06545
INSP. #: 695103024



PHOTO 1: LOCATION

PHOTO 2: WELL SIGN IS POSTED ON GAS METER HOUSE, AT TIME OF INSPECTION METER HOUSE DOOR WAS TIED OPEN MAKING SIGN NOT VISIBLE. **POST SIGN IN COMPLIANCE WITH RULE 210.b. CA DATE 10-23-20**

Inspection Photos
Location Name: HURT 1-4
API#: 05-067-06545
INSP. #: 695103024



PHOTO 3: MATURE FLOWERING NOXIOUS WEEDS ALL AROUND LOCATION AND ON INTERIM RECLAMATION AREA.
CONTROL WEEDS CA DATE 7-27-20.

PHOTO 4: ANOTHER IMAGE OF NOXIOUS WEEDS

Inspection Photos
Location Name: HURT 1-4
API#: 05-067-06545
INSP. #: 695103024



PHOTO 5: NFPA STICKER FAIDED AND FALLING APART. POST NFPA STICKERS IN COMPLIANCE WITH RULE 210.d. CA DATE 10-23-20.

PHOTO 6: NFPA STICKER IS FAIDED AND ALMOST NOT LEGIBLE ALSO THERE IS NO TANK CAPACITY POSTED ON TANK. POST SIGNS IN COMPLIANCE WITH RULE 210.d ca date 10-23-20.