

Inspection Photos
Location Name: HUBER LEWIS 2-4
API#: 05-067-07674
INSP. #: 695103026



PHOTO 1: LOCATION



PHOTO 2: WELL SIGN

Inspection Photos
Location Name: HUBER LEWIS 2-4
API#: 05-067-07674
INSP. #: 695103026



PHOTO 3: MATURE FLOWERING NOXIOUS WEEDS ALL AROUND LOCATION AND ON INTERIM RECLAMATION AREA.
CONTROL WEEDS CA DATE 7-27-20.



PHOTO 4: AFTER NOTICING WHAT APPEARS TO BE USED OIL RUNNING DOWN CONCRETE PUMPJACK PAD I KICKED FRESH LAID DIRT ASIDE AND REVEALED AN AREA OF IMPACTED SOIL ON GROUND NEXT TO PUMPJACK ENGINE. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. CA DATE 10-23-20.