

Inspection Photos
July 24, 2020

Location Name: Pintail SWD Location ID 446527; Spill ID 477094



Sign at entrance to Location ID: 446527.



Inspection Photos

July 24, 2020

Location Name: Pintail SWD Location ID 446527; Spill ID 477094



Approximate 1"x 1.5" hole in tank.



Approximate 1"x 1.5" hole in tank.



Inspection Photos
July 24, 2020

Location Name: Pintail SWD Location ID 446527; Spill ID 477094



Stair supports deteriorating with rebar exposed on liner.

Concrete weight/anchor to hold liner in place deteriorating. Note the folds in liner.



Inspection Photos
July 24, 2020

Location Name: Pintail SWD Location ID 446527; Spill ID 477094



Compromised tank in left of photo. Tank #s 0601 and 0602 show insulation removed and tank exposed similar to the compromised tank.



Pooling oil and salt staining has been addressed from the June 20, 2020 inspection.



Inspection Photos
July 24, 2020

Location Name: Pintail SWD Location ID 446527; Spill ID 477094



Insulation removed exposing Tank # 0601 surface.



Salt staining and trash/debris has been addressed from the June 20, 2020 inspection.



Inspection Photos

July 24, 2020

Location Name: Pintail SWD Location ID 446527; Spill ID 477094



Pooling oil and salt staining has been addressed from the June 20, 2020 inspection.



Pooling oil and salt staining has been addressed from the June 20, 2020 inspection.



Inspection Photos

July 24, 2020

Location Name: Pintail SWD Location ID 446527; Spill ID 477094



Absorbent material at the base of tanks.




Surface staining at load out. Hydrocarbon odor noted with apparent wood fiber mixed into soil.



Inspection Photos
July 24, 2020

Location Name: Pintail SWD Location ID 446527; Spill ID 477094



Surface staining at load out. Hydrocarbon odor noted with apparent wood fiber mixed into soil.

Surface staining has been addressed from the June 20, 2020 inspection.



Inspection Photos

July 24, 2020

Location Name: Pintail SWD Location ID 446527; Spill ID 477094



Concrete weight/anchor with rebar and valve handles with potential to puncture or compromise liner.



Concrete weight/anchor with other debris on liner with the potential to puncture or compromise liner. Note how liner is wind blown with folds.



Inspection Photos
July 24, 2020

Location Name: Pintail SWD Location ID 446527; Spill ID 477094



Surface staining.



Surface staining.