

# Inspection Photos

API: 055-06221

Operator: PETROGLYPH OPERATING CO INC

Inspection Date: 7/27/2020



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06221 | Date: 7/27/2020

## Inspection Photos



**Photo 1.** Facing southeast along the access road. Rock check dams were installed along the side of the road but have since failed. The rock has been displaced as shown by arrow.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06221 | Date: 7/27/2020

## Inspection Photos



**Photo 2.** Signs of stormwater flowing down the road causing erosion near the State 7W location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06221 | Date: 7/27/2020

## Inspection Photos



**Photo 3.** The check dams have filled in with sediment which are not maintained.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06221 | Date: 7/27/2020

## Inspection Photos



**Photo 4.** Facing east toward the location. The vegetation appears to be establishing well in areas of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06221 | Date: 7/27/2020

## Inspection Photos



**Photo 5.** Facing northwest toward the location. The vegetation appears to be establishing well in areas of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06221 | Date: 7/27/2020

## Inspection Photos



**Photo 6.** Facing northwest toward the location. The vegetation appears to be establishing well in areas of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06221 | Date: 7/27/2020

## Inspection Photos



**Photo 7.** There is plastic netting debris along the southeast cut slope that needs to be removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06221 | Date: 7/27/2020

## Inspection Photos



**Photo 8.** Facing northwest at the south side of the location. This area is bare of vegetation and is not stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06221 | Date: 7/27/2020

## Inspection Photos



**Photo 9.** Facing southeast at the south side of the location. The access road continues toward the State 10WB. This check damn has filled in with sediment. The side of road needs to be seeded and stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06221 | Date: 7/27/2020