

Inspection Photos

Location Name: MARALEX RESOURCES INC SULFUR GULCH 9-98-10-69S98W /10NWNW

Location ID: 312654



Photo #1629 from entrance to location



Photo #1630 from entrance to location

Inspection Photos

Location Name: MARALEX RESOURCES INC SULFUR GULCH 9-98-10-69S98W /10NWNW

Location ID: 312654



Photo #1046 from inspection #699800986 conducted on 4/27/20.




Photo #1631 Tank capacity, contents and NFPA labels weathered and not legible.

Inspection Photos

Location Name: MARALEX RESOURCES INC SULFUR GULCH 9-98-10-69S98W /10NWNW

Location ID: 312654



Photo #1048 from inspection #699800986 conducted on 4/27/20.



Photo #1632 Multiple places with debris on location.

Inspection Photos

Location Name: MARALEX RESOURCES INC SULFUR GULCH 9-98-10-69S98W /10NWNW

Location ID: 312654



Photo #1050 from inspection #699800986 conducted on 4/27/20.



Photo #1633 Multiple places with debris on location.