

Inspection Photos

Location Name: MARALEX RESOURCES INC USA-69S98W /18NESW

Location ID: 312548



Photo #1638 from entrance to location



Photo #1052 from inspection #699800988 conducted on 4/27/20.

Inspection Photos

Location Name: MARALEX RESOURCES INC USA-69S98W /18NESW

Location ID: 312548



Photo #1639 Battery sign is weathered and not legible.



Photo #1053 from inspection #699800988 conducted on 4/27/20.

Inspection Photos

Location Name: MARALEX RESOURCES INC USA-69S98W /18NESW

Location ID: 312548



Photo #1640 Tank capacity, contents and NFPA label weathered and not legible.

Photo #1055 from inspection #699800988 conducted on 4/27/20.

Inspection Photos

Location Name: MARALEX RESOURCES INC USA-69S98W /18NESW

Location ID: 312548



Photo #1642 Multiple places with debris on location.



Photo #1056 from inspection #699800988 conducted on 4/27/20.

Inspection Photos

Location Name: MARALEX RESOURCES INC USA-69S98W /18NESW

Location ID: 312548



Photo #1643 Multiple places with debris on location.



Photo #1057 from inspection #699800988 conducted on 4/27/20.

Inspection Photos

Location Name: MARALEX RESOURCES INC USA-69S98W /18NESW

Location ID: 312548



Photo #1644 Unused supplies and equipment.



Photo #1060 from inspection #699800988 conducted on 4/27/20.

Inspection Photos

Location Name: MARALEX RESOURCES INC USA-69S98W /18NESW

Location ID: 312548



Photo #1641 Tank berm has eroded.