

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/29/2020

Submitted Date:

07/29/2020

Document Number:

701001060

**FIELD INSPECTION FORM**

Loc ID 305024 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10112  
 Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC  
 Address: 5057 KELLER SPRINGS RD STE 650  
 City: ADDISON State: TX Zip: 75001

**Findings:**

- 9 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name  | Phone | Email                           | Comment |
|---------------|-------|---------------------------------|---------|
| Beard, Alyssa |       | regulatory@foundationenergy.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 277636      | WELL | PR     | 08/01/2019  | GW         | 125-09270 | ALLISON 32-5  | PR          |

**General Comment:**

Routine Inspection

**Location**

**Lease Road:**

|                    |                           |       |  |
|--------------------|---------------------------|-------|--|
|                    | Type Access               |       |  |
| comment:           | Two track through pasture |       |  |
| Corrective Action: |                           | Date: |  |

Overall Good:

**Signs/Marker:**

|                    |                    |       |  |
|--------------------|--------------------|-------|--|
|                    | Type WELLHEAD      |       |  |
| Comment:           | Lease sign by unit |       |  |
| Corrective Action: |                    | Date: |  |

Emergency Contact Number:

|                    |  |       |  |
|--------------------|--|-------|--|
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |  |
|------|------|--------|--|--|--|
|      |      |        |  |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

|                    |                                       |       |  |
|--------------------|---------------------------------------|-------|--|
|                    | Type PUMP JACK                        |       |  |
| Comment:           | Metal panels around unit and wellhead |       |  |
| Corrective Action: |                                       | Date: |  |

**Equipment:**

|                           |  |       |  |  | corrective date |
|---------------------------|--|-------|--|--|-----------------|
| Type: Ancillary equipment | # 2                                    |       |  |  |                 |
| Comment:                  | Electric panel and telemetry equipment |       |  |  |                 |
| Corrective Action:        |  | Date: |  |  |                 |
| Type: Pump Jack           | # 1                                    |       |  |  |                 |
| Comment:                  | Jensen unit stored neatly on location  |       |  |  |                 |
| Corrective Action:        |  | Date: |  |  |                 |
| Type: Gas Meter Run       | # 1                                    |       |  |  |                 |
| Comment:                  |  |       |  |  |                 |
| Corrective Action:        |  | Date: |  |  |                 |
| Type: Vertical Separator  | # 1                                    |       |  |  |                 |
| Comment:                  | Vertical gas separator 50% buried      |       |  |  |                 |
| Corrective Action:        |  | Date: |  |  |                 |
| Type: Prime Mover         | # 1                                    |       |  |  |                 |
| Comment:                  | Electric motor                         |       |  |  |                 |
| Corrective Action:        |  | Date: |  |  |                 |

|                    |  |       |  |
|--------------------|--|-------|--|
| <b>Venting:</b>    |  |       |  |
| Yes/No             |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

|                    |  |       |  |
|--------------------|--|-------|--|
| <b>Flaring:</b>    |  |       |  |
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Inspected Facilities**

Facility ID: 277636 Type: WELL API Number: 125-09270 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing. Casing production. Free flowing up the casing](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            | Compaction              | Pass                  |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description    | URL   |
|--------------|----------------|---|
| 701001075    | location photo | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5213499">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5213499</a> |