

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/29/2020

Submitted Date:

07/29/2020

Document Number:

701001069

**FIELD INSPECTION FORM**

Loc ID 304359 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10112  
Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC  
Address: 5057 KELLER SPRINGS RD STE 650  
City: ADDISON State: TX Zip: 75001

**Findings:**

10 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Beard, Alyssa		regulatory@foundationenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
260193	WELL	PR	08/01/2019	GW	125-08302	KAUBLE 12-5	PR

**General Comment:**

Routine Inspection

**Location**

<b>Lease Road:</b>			
	Type Access		
	comment: <a href="#">Dirt road through pasture</a>		
Corrective Action:			Date:

Overall Good:

<b>Signs/Marker:</b>			
	Type WELLHEAD		
	Comment: <a href="#">Lease sign by wellhead</a>		
Corrective Action:			Date:
	Type TANK LABELS/PLACARDS		
	Comment: <a href="#">Metal sign by water tank</a>		
Corrective Action:			Date:

Emergency Contact Number:			
	Comment: <input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>		Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
	Type TANK BATTERY		
	Comment: <a href="#">Metal panels around water tank</a>		
Corrective Action:			Date:
	Type WELLHEAD		
	Comment: <a href="#">Metal panels around wellhead and meter run</a>		
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Vertical Separator	# 2		
Comment:	<a href="#">1-Vertical gas separator 50% buried by meter run</a> <a href="#">1-Gas separator in metal box</a>		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	<a href="#">Telemetry equipment</a>		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		39.914280,-102.220480

Comment: [Fiberglass water tank 50% buried](#)

Corrective Action:		Date:	
--------------------	--	-------	--

**Paint**

Condition	
Other (Content)	
Other (Capacity)	214bbbs
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate

Comment:

Corrective Action:		Date:	
--------------------	--	-------	--

**Venting:**

Yes/No	
Comment:	
Corrective Action:	
	Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	
	Date:

**Inspected Facilities**

Facility ID: 260193 Type: WELL API Number: 125-08302 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing. Casing production](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701001083	location photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5213507">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5213507</a>