

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/23/2020

Submitted Date:

07/23/2020

Document Number:

697001704**FIELD INSPECTION FORM**Loc ID 311483 Inspector Name: Peterson, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**14 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_cogccengineering@state.co.us	
,		cogccinspections@anadarko.com	
Kraich, Adam		adam.kraich@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
280382	WELL	SI	12/01/2018	OW	123-23264	STAR O 15-23	TA
280453	WELL	SI	12/01/2018	OW	123-23279	STAR O 15-10	TA
280454	WELL	SI	12/01/2018	GW	123-23278	STAR O 15-9	TA

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	x 3		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Miscellaneous pipe, fittings and old sign around separator area. See attached photos.		
Corrective Action:	Comply with Rule 603.f .	Date:	10/26/2020

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Barbed wire topped chain link		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Barbed wire topped chain link		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	Barbed wire topped chain link		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Barbed wire topped chain link		
Corrective Action:		Date:	

Equipment:				corrective date	
Type: Ancillary equipment	# 2				
Comment:	ECD scrubbers				
Corrective Action:					Date:
Type: Bradenhead	# 3				
Comment:	Bradenhead valves are exposed at surface.				
Corrective Action:					Date:
Type: Plunger Lift	# 3				
Comment:					
Corrective Action:					Date:
Type: Bird Protectors	# 2				
Comment:					
Corrective Action:					Date:
Type: Emission Control Device	# 1				
Comment:					
Corrective Action:					Date:
Type: Horizontal Heated Separator	# 1				
Comment:					
Corrective Action:					Date:
Type: Gas Meter Run	# 0				
Comment:	Gas sales meter has been removed. See attached photo.				
Corrective Action:					Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLS	PBV FIBERGLASS		,	
Comment:	60 bbls					
Corrective Action:						Date:

Paint

Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		,
Comment:					

Corrective Action:				Date:	
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:				Date:	
Flaring:					
Type					
Comment:					
Corrective Action:				Date:	

Inspected FacilitiesFacility ID: 280382 Type: WELL API Number: 123-23264 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: Last produced 11/2018. Well was found in state of Temporary Abandonment. Gas sales line has been removed from separator and gas sales meter has been removed. See attached photos.Corrective Action: Perform successful mechanical integrity test. If a successful MIT can not be performed within 90 day CA time the well must be plugged within 3 months per Rule 326 and 208. Date: 10/26/2020Facility ID: 280453 Type: WELL API Number: 123-23279 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: Last produced 11/2018. Well was found in state of Temporary Abandonment. Gas sales line has been removed from separator and gas sales meter has been removed. See attached photos.Corrective Action: Perform successful mechanical integrity test. If a successful MIT can not be performed within 90 day CA time the well must be plugged within 3 months per Rule 326 and 208. Date: 10/26/2020Facility ID: 280454 Type: WELL API Number: 123-23278 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: Last produced 11/2018. Well was found in state of Temporary Abandonment. Gas sales line has been removed from separator and gas sales meter has been removed. See attached photos.Corrective Action: Perform successful mechanical integrity test. If a successful MIT can not be performed within 90 day CA time the well must be plugged within 3 months per Rule 326 and 208. Date: 10/26/2020

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary On Thursday 7/23/2020 at approximately 09:30 hours, I, Inspector Tom Peterson, conducted an on-site inspection at the Anadarko Star O 15-23 Pad location #331483 in Weld County, Colorado.</p> <p>While there, I observed unused equipment around the separator area and that the gas sales line from the separator to the gas sales meter had been disconnected and the gas sales meter had been removed. The wells are now in a TA status and requires a MIT to be performed. During this inspection the following possible compliance issues were observed: Rule 326. and Rule 208. with a corrective action date of 10/26/2020, and Rule 603.f. with a corrective action date of 10/26/2020.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of the inspection report.</p>	petersont	07/23/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402450084	INSPECTION SUBMITTED	402450084.pdf
402451200	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5206040
697001705	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5205355