

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/21/2020

Submitted Date:

07/29/2020

Document Number:

695102994**FIELD INSPECTION FORM**

Loc ID 311904 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10464Name of Operator: CATAMOUNT ENERGY PARTNERS LLCAddress: 1801 BROADWAY #1000City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Fischer, Reed	(303) 981-2921	Inspections@catamountep.com	All Inspections
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214350	WELL	PR	09/01/2019	GW	067-05749	V D HELTON 1	PR
216569	WELL	PR	01/15/1999	GW	067-08175	HELTON 1A	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type TANK BATTERY

Comment:

Corrective Action:

Date:

Equipment:

corrective date

Type: Bradenhead

2

Comment: BOTH ARE PLUMBED TO SURFACE

Corrective Action:

Date:

Type: Gas Meter Run

2

Comment: BOTH CAL. LOGS INDICATE GAS METERS HAS BEEN CALIBRATED WITHIN THE LAST YEAR.

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	BV STEEL		37.107494,-104.754232
Comment:					
Corrective Action:					Date:

Paint

Condition Adequate

Other (Content)

Other (Capacity) 40 BBL

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 214350 Type: WELL API Number: 067-05749 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

Facility ID: 216569 Type: WELL API Number: 067-08175 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

COGCC Comments

Comment

User

Date

I TOM BEARDSLEE MODIFIED THIS INSPECTION REPORT ON 7-30-20 DUE TO A MISTAKE I MADE ON SIGHTING THAT THERE WAS NO 911 INCLUDED ON THE WELLHEAD SIGN. AFTER REVIEWING THE PHOTOS THERE IS A STICKER WITH 911 ON THE SIGN. I SPOKE WITH THE OPERATOR AND ADVISED THEM THAT THE 911 STICKER IS TO SMALL AND STILL A VIOLATION.

beardslt

07/30/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402455566	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5213041
402456412	INSPECTION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5213845
695102995	INSPECTION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5213030