

# Inspection Photos

7/24/2020

Operator: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 334754

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850  
Location ID: 334754



**Photo 1:** Photo taken from the east end of the production area, facing south. Photos 1-4 provide an overview of the Location from south, southwest, northwest to north.



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 334754



**Photo 2:** See comments under photo 1.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850  
Location ID: 334754



**Photo 3:** See comments under photo 1. Photo also shows unused equipment, or equipment not needed for production stored on the western areas of the Location.

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 334754



**Photo 4:** See comments under photo 1. Photo also shows unused equipment, or equipment not needed for production stored on the Location.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850  
Location ID: 334754



**Photo 5:** Photo taken from the west end of the Location. Photo shows unused equipment, or equipment not needed for production stored on the western areas of the Location.





## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 334754



**Photo 6:** Photo taken from the southwestern interim areas, facing north. Photo shows erosion degradation on the slopes; Slopes do not appear to be sufficiently stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850  
Location ID: 334754



**Photo 7:** Photo taken from the southwestern interim areas, facing southwest. Photo shows erosion degradation on the slopes; Slopes do not appear to be sufficiently stabilized.

