

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

07/24/2020

Submitted Date:

07/24/2020

Document Number:

700402579**FIELD INSPECTION FORM**
 Loc ID 336550 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10342Name of Operator: WOODARD* SANDRA KAddress: 602 OURAY AVENUECity: GRAND JUNCTION State: CO Zip: 81501**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
,	970-261-6589	3oilwells@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229623	WELL	SI	06/01/2019	OW	103-07280	STAGNER RECTOR 7	SI

General Comment:

A follow up inspection of FIR documents:

- 1) 679705374 dated 9-6-2019.
- 2) 700400162 dated 2-24-2020.
- 3) 700401505 dated 5-15-2020.

The following compliance issues are uncompleted:

- 1) Stained & oily soil around pump jack. Photo 2. Complete by 10-9-2019.
- 2) Open bucket of fluid next to well head. Photo 3. Complete by 10-9-2019.

This is a summary of inspection report 700402579.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	911		
Corrective Action:		Date:	

Good Housekeeping:			
Type	OTHER		
Comment:	Stained soil around well head and flow line.		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e.	Date:	10/09/2019
Type	OTHER		
Comment:	Open bucket of fluid next to well head. Bucket without wildlife protection & could be tipped over.		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e.	Date:	10/09/2019

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	Partial fencing.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No	YES		
Comment:	Casing open to atmosphere. Images and volumes documented in prior inspections.		
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 229623 Type: WELL API Number: 103-07280 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Last recorded production May 2019.

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402450894	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5205429
402451337	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5206208
700402580	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5205418