

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/30/2020

Submitted Date:

07/30/2020

Document Number:

699801536**FIELD INSPECTION FORM**Loc ID 322011 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10310Name of Operator: FRAM OPERATING LLCAddress: 5525 N UNION BLVD #200City: COLORADO State: CO Zip: 80918**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
, Engineering		dnr_cogccengineering@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
Cook, David	(719) 314-1623	dave@framamericas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
286534	WELL	SI	10/31/2006	GW	029-06101	HAMILTON 32-4	TA

General Comment:**COGCC Inspection Report Summary**

On Thursday 7/30/20 at approximately 13:00 hours, I, Inspector Corey De Paolo,
Conducted an on-site inspection at FRAM OPERATING LLC HAMILTON-613S95W /32SESW,
Location #322011 in Delta County Colorado.

During this inspection the following possible compliance issues were observed: MIT required on well. With a corrective action date of 10/30/20.

A follow up on this site inspection needs to be conducted to ensure the
compliance issues have been corrected to comply with COGCC rules.
This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action:		Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 286534 Type: WELL API Number: 029-06101 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: Last MIT preformed 10/17/12. MIT required on well.Corrective Action: A mechanical integrity test shall be performed on each temporarily abandoned well on five year intervals from the date of the initial mechanical integrity test was performed. Preform MIT on well. Date: 10/30/2020

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
All equipment has been remove from location. Only the wellhead remains.	depaoloc	07/30/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699801537	Photos for Insp. #699801536	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5214452