

FORM  
INSPRev  
X/15State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/31/2020

Submitted Date:

07/31/2020

Document Number:

700701242

## FIELD INSPECTION FORM

 Loc ID 335538 Inspector Name: Ramsey, Scott On-Site Inspection  2A Doc Num: \_\_\_\_\_
**Operator Information:**
 OGCC Operator Number: 10447  
 Name of Operator: URSA OPERATING COMPANY LLC  
 Address: 950 17TH STREET, SUITE 1900  
 City: DENVER State: CO Zip: 80202
**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 15 Number of Comments  
 2 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
 PREVIOUS INSPECTIONS THAT HAVE NOT  
 BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
291065	WELL	PR	03/01/2020	GW	045-14284	VALLEY FARMS F2	PR
291066	WELL	PR	03/01/2020	GW	045-14285	VALLEY FARMS F3	PR
291067	WELL	PR	03/01/2020	GW	045-14286	VALLEY FARMS F5	PR
291072	WELL	PR	03/01/2020	GW	045-14289	VALLEY FARMS F7	PR
291073	WELL	PR	03/01/2020	GW	045-14290	VALLEY FARMS F1	PR
296414	WELL	PR	03/01/2020	GW	045-16011	VALLEY FARMS F8	PR
296415	WELL	PR	07/11/2013	GW	045-16012	VALLEY FARMS FEDERAL F14	PR
301818	WELL	PR	04/04/2013	GW	045-18286	Valley Farms F-1H	PR
301819	WELL	XX	04/27/2018	LO	045-18287	Valley Farms F21	XX

**General Comment:**

## COGCC Inspection Report Summary

On Friday 7/31/20 at approximately 1200, I, Inspector Scott Ramsey, conducted a routine inspection at Ursa Valley Farms F, at Location # 3335538 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year.

During this inspection the following possible compliance issues were observed:

- Thief hatch is open
- Staining
- Debris

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	<input type="text" value="911"/>		
Corrective Action:	<input type="text"/>		Date: _____
<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Gauge hatch open or not sealed.		
Corrective Action:	Close and seal gauge hatches when not accessing tank		Date: <u>08/01/2020</u>
Type	DEBRIS		
Comment:	random debris around location and staining under load out valves		
Corrective Action:	remove debris and stained gravel		Date: <u>08/07/2020</u>
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:	<input type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 1		
Comment:	chemical tank at well heads		
Corrective Action:			Date:
Type: Plunger Lift	# 8		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 9		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heater Treater	# 1		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 5		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 9		
Comment:			
Corrective Action:			Date:
Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 9		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	300 BBLs	STEEL AST		,	
Comment:	one tanks is heated					
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	8	300 BBLs	STEEL AST		,
Comment:	two tanks are in shared containment with condensate tanks all other tanks are in a seperate containment.				
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	Ignitor/Combustor
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	291065	Type:	WELL	API Number:	045-14284	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	291066	Type:	WELL	API Number:	045-14285	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	291067	Type:	WELL	API Number:	045-14286	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	291072	Type:	WELL	API Number:	045-14289	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	291073	Type:	WELL	API Number:	045-14290	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	296414	Type:	WELL	API Number:	045-16011	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	296415	Type:	WELL	API Number:	045-16012	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	301818	Type:	WELL	API Number:	045-18286	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:					Date:				

Facility ID: 301819 Type: WELL API Number: 045-18287 Status: XX Insp. Status: XX

**Environmental**

**Spill/Remediation:**

Comment:

Corrective Action:  Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms		Berms				
Ditches		Culverts				
Gravel		Ditches				
Blankets		Gravel				

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700701247	Photos for Valley Farms F	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5214961">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5214961</a>