



Captiva
Energy Partners

Captiva Energy Partners LLC


Inspection Compliance Photos

Date of COGCC Inspection: May 8, 2020

Location Name: McCoy Pad 13-33

Location ID: 428105

July 27-30, 2020



McCoy Tank Battery

McCoy Pad 13-33
Location ID: 428105



New McCoy Battery Sign Installed



Missing Crude Oil Tank Placard Installed

McCoy Pad 13-33
Location ID: 428105



Produced Water Tank Volume Label

McCoy Pad 13-33
Location ID: 428105



Downed section of separator fence has been repaired

McCoy Pad 13-33
Location ID: 428105



123 000 . 00 . 00 / 07 . 27 . 2020

McCoy Pad 13-33
Location ID: 428105



Mountain West Vegetation
Management Inc. sprayed location
weeds on June 10, 2020

McCoy Pad 13-33
Location ID: 428105



Compressor and Sump Removed

McCoy Pad 13-33
Location ID: 428105



123 000 . 00 . 00 / 07 27 2020

Sump and Stained Soil Removed




McCoy Pad 13-33
Location ID: 428105

123 000.00.00 / 07.27.2020

Current DCP Meter Calibrations Located in Meter House

DCP Meter Calibrations Dated May 13, 2020



McCoy Pad 13-33, Location ID: 428105

Location Access Road and Pad After Grading

McCoy Pad 13-33
Location ID: 428105
7/30/2020




Lease road coming on to McCoy Pad 13-33 pad
(looking northeast)

McCoy Pad 13-33
Location ID: 428105
7/30/2020



Graded drive west of tank battery
(looking north)

Location Access Road and Pad After Grading



**Pad area east of wellheads
(looking north)**



**Pad area between wellheads and separators
(looking north)**