

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/30/2020

Submitted Date:

08/01/2020

Document Number:

696103435**FIELD INSPECTION FORM**Loc ID 305261 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1775 SHERMAN STREET - STE 3000City: DENVER State: CO Zip: 80203**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
276058	WELL	SI	03/01/2019	OW	123-22723	PHINNEY 44-10	SI

General Comment:[This is a WELL inspection.](#)[Well\(s\): 1: Shut-In | SI.](#)[Battery: Inactive | Shut-down.](#)[Centralized Battery serves 4 Location IDs \(305261, 305198, 305858, 305859\).](#)[\(Well\(s\): 4: Shut-In | SI\).](#)[Refer to Field Inspection Report doc. #696103370 and/or Location ID #305261 for Battery / Facility, Equipment info.](#)[Follow-up to Field Inspection Report doc. #696103370 dated 07/21/2020.](#)

Location				
Lease Road:				
Type	Access			
comment:	Adequate			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Type				
Comment:	Refer to Field Inspection Report doc. #696103370 and/or Location ID #305261 for Battery / Facility, Equipment info.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Good Housekeeping:				
Type	WEEDS			
Comment:	<p>Prior insp: Weed encroachment at wellsite. Refer to Rule 603.f for guidance. Remove, manage, & control weeds around wellsite. Comply with Rule 603.f. Corrective Action date: 08/05/2020.</p> <p>This insp: * Weeds around wellsite NOW appear mitigated. See photos #1, 2.</p>			
Corrective Action:				Date:
Overall Good: <input checked="" type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:	Iron panel.			
Corrective Action:				Date:
Type				
Comment:	Refer to Field Inspection Report doc. #696103370 and/or Location ID #305261 for Battery / Facility, Equipment info.			
Corrective Action:				Date:

Equipment:				corrective date
Type: Bradenhead	# 1			
Comment:	Appears plumbed to surface.			
Corrective Action:				Date:
Type: Plunger Lift	# 1			
Comment:				
Corrective Action:				Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
			CENTRALIZED BATTERY		40.497240,-104.528100	
Comment:	Centralized Battery serves 4 Location IDs (305261, 305198, 305858, 305859). Refer to Field Inspection Report doc. #696103370 and/or Location ID #305261 for Battery / Facility, Equipment info.					
Corrective Action:						Date:

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	276058	Type:	WELL	API Number:	123-22723	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose:		<input checked="" type="checkbox"/> Shut In		<input type="checkbox"/> Temporarily Abandoned		Reminder: PRODUCTION RECORDS			
Comment:		<div>Shut-In SI. Observed production valves shut. COGCC records indicate last production: 02/2019.</div>							
Corrective Action:								Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On THU 07/30/2020 at approximately 10:19 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: PDC ENERGY INC Location Name: PHINNEY-66N64W /10SESE Location ID: 305261 Well Name: Phinney 44-10 API: 05-123-22723 Location County: Weld County, Colorado Weather: Partly cloudy, dry.</p> <p>While there, I observed: Well(s): 1: Shut-In SI. Battery: Inactive Shut-down.</p> <p>Centralized Battery serves 4 Location IDs (305261, 305198, 305858, 305859). (Well(s): 4: Shut-In SI).</p> <p>Refer to Field Inspection Report doc. #696103370 and/or Location ID #305261 for Battery / Facility, Equipment info.</p> <p>Follow-up to Field Inspection Report doc. #696103370 dated 07/21/2020.</p> <p>During this inspection, the following prior possible compliance issues appear to be addressed: 1.) Weed encroachment at wellsite. Refer to Rule 603.f for guidance. Remove, manage, & control weeds around wellsite. Comply with Rule 603.f. Corrective Action date: 08/05/2020. * Weeds around wellsite NOW appear mitigated. See photos #1, 2.</p> <p>During this inspection, NO New/Current possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	08/01/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696103436	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5215029