

Inspection Photos  
Operator: ConocoPhillips  
API: 067-08199  
Date: 7/28/2020



Photo 1. View of access road from the eastern portion facing westward. Revegetation is progressing with western wheatgrass, squirreltail, and smooth brome, as well as forbs such as yellow sweetclover.





Photo 2. View of the central portion of the access road facing westward. Revegetation is progressing here.





Photo 3. View of the western portion of the access road, facing northward. Revgetation is progressing, although musk thistles need to be controlled.





Photo 4. View of area at cement BMP, needing additional stabilization. Erosional downcutting is approximately 2.5 feet deep.





Photo 5. View of the project area from the southwestern corner facing center. Vegetation is becoming established.





Photo 6. View of the southern project area from the southwestern corner facing eastward.





Photo 7. View of drainage channel that was re-connected at reclamation. Drainage elevation is approximately the same as up-stream elevation and appears to be functioning.





Photo 8. View of perimeter wattle that needs to be removed.





Photo 9. View of reference area vegetation comprised of ponderosa pine woodland in post-fire recovery vegetative condition, with dense gambel oak and scattered junipers in the understory.