

# Inspection Photos

7/31/2020

Operator: CHEVRON USA INC - 16700

Location ID: 382974

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location ID: 382974



**Photo 1:** Photo taken from the east end of the location facing southwest. Photos 1-4 provide an overview of the Location and reclamation from southwest, west, northwest to north.

Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location ID: 382974



**Photo 2:** See comments under photo 1.



Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location ID: 382974



**Photo 3:** See comments under photo 1.

Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location ID: 382974



**Photo 4:** See comments under photo 1.



Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location ID: 382974



**Photo 5:** Photo taken from the northeast end of the Location, facing west. Photo shows 1 of 2 areas observed on the Location where additional reclamation activities appear to have been conducted.



Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location ID: 382974



**Photo 6:** Photo taken from the south end of the Location, facing north. Photo shows wattle BMPs on Location have not been installed in accordance with good engineering practices; BMPs were placed/staked upon the soil surface, and have not been trenched and backfilled; Wattle BMPs are not in proper functioning condition. Stormwater has cut under the wattles and erosion degradation is evident



Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location ID: 382974



**Photo 7:** See comments under photo 6.



Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location ID: 382974



**Photo 8:** Photo taken from the access road on the north end of the Location, facing west.

