

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/03/2020

Submitted Date:

08/03/2020

Document Number:

700402720

**FIELD INSPECTION FORM**

Loc ID 315358 Inspector Name: Moran, Rick On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 74290  
Name of Operator: RETAMCO OPERATING INC  
Address: PO BOX 790  
City: RED LODGE State: MT Zip: 59068

**Findings:**

- 5 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Johnson, Joe	406-446-1568	joejohnson@retamco.com	
Glennon, Joe	406-446-1568	joeglennon@retamco.com	
Gose, Tom	210-216-0819	tomgose@retamco.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230694	WELL	PR	04/01/2020	GW	103-08362	PHILADELPHIA CREEK 21	PR

**General Comment:**

A follow up inspection of FIR document 700401338.

The following compliance issues were resolved:

- 1) Fallen deadman markers in SE & NW corners.
- 2) Signs. Update with current operator & phone number.

This is a summary of inspection report 700402720.

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	PIT		
Comment:			
Corrective Action:		Date:	

**Equipment:**

Type			corrective date
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 230694 Type: WELL API Number: 103-08362 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass					

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

Type: Blowdown                      Lined: NO                      Pit ID:                      Lat:                      Long:

Reference Point: \_\_\_\_\_                      Other: \_\_\_\_\_                      Length: \_\_\_\_\_                      Width: \_\_\_\_\_

**Lining:**

Liner Type:    Liner Condition:

Comment: Well.

Corrective

Date: \_\_\_\_\_

**Fencing:**

Fencing Type: Wildlife    Fencing Condition: Adequate

Comment: \_\_\_\_\_

Corrective

Date: \_\_\_\_\_

**Netting:**

Netting Type: Mesh    Netting Condition: Good

Comment: \_\_\_\_\_

Corrective

Date: \_\_\_\_\_

Anchor Trench Present:                      Oil Accumulation: NO                      2+ feet Freeboard: YES

Comment: \_\_\_\_\_

Corrective

Date: \_\_\_\_\_

Type: Blowdown                      Lined: NO                      Pit ID:                      Lat:                      Long:

Reference Point: \_\_\_\_\_                      Other: \_\_\_\_\_                      Length: \_\_\_\_\_                      Width: \_\_\_\_\_

**Lining:**

Liner Type:    Liner Condition:

Comment: Separator.

Corrective

Date: \_\_\_\_\_

**Fencing:**

Fencing Type: Wildlife    Fencing Condition: Adequate

Comment: \_\_\_\_\_

Corrective

Date: \_\_\_\_\_

**Netting:**

Netting Type: Mesh    Netting Condition: Good

Comment: \_\_\_\_\_

Corrective

Date: \_\_\_\_\_

Anchor Trench Present:

Oil Accumulation: NO

2+ feet Freeboard: YES

Comment:

Corrective

Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700402721	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5215701">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5215701</a>