

Inspection Photos
Location Name: DIXIECUP 31-12 TR
API#: 05-071-08671
INSP. #: 695103045



PHOTO 1: LOCATION



PHOTO 2: WELL SIGN



Inspection Photos

Location Name: DIXIECUP 31-12 TR

API#: 05-071-08671

INSP. #: 695103045



**PHOTO 3: UNUSED RISERS NEAR WEST WELLHEAD NOT MARKED AS TO WHAT ITS USED FOR AND NO LO/TO.
REMOVE OR PROPERLY MARK AND LO/TO PER RULE 603.f.
CA DATE 11-3-20.**



**PHOTO 4: UNUSED RISERS NEAR WEST WELLHEAD NOT MARKED AS TO WHAT ITS USED FOR AND NO LO/TO.
REMOVE OR PROPERLY MARK AND LO/TO PER RULE 603.f.
CA DATE 11-3-20.**



Inspection Photos

Location Name: DIXIECUP 31-12 TR

API#: 05-071-08671

INSP. #: 695103045



**PHOTO 5: UNUSED RISERS NEAR EAST WELLHEAD NOT MARKED AS TO WHAT ITS USED FOR AND NO LO/TO.
REMOVE OR PROPERLY MARK AND LO/TO PER RULE 603.f.
CA DATE 11-3-20.**



**PHOTO 6: UNUSED RISERS NEAR METER HOUSE NOT MARKED AS TO WHAT ITS USED FOR AND NO LO/TO.
REMOVE OR PROPERLY MARK AND LO/TO PER RULE 603.f.
CA DATE 11-3-20.**

Inspection Photos

Location Name: DIXIECUP 31-12 TR

API#: 05-071-08671

INSP. #: 695103045



**PHOTO 7: TRASH STORED IN METER HOUSE. REMOVE TRASH
PER RULE 603.f. CA DATE 11-3-20.**

**PHOTO 8: NO FREEBOARD MARKER IN EAST PIT. INSTALL
FREEBOARD MARKER PER RULE 902.b. CA DATE 11-3-20**

Inspection Photos

Location Name: DIXIECUP 31-12 TR

API#: 05-071-08671

INSP. #: 695103045



PHOTO 9: BMP'S ON ACCESS ROAD ARE FAILING AND OR IMPROPERLY INSTALLED. REPAIR AND INSTALL BMP'S TO CONTROL STORMWATER AND SEDIMENT FROM WASH DOWN ROADWAY PER RULE 1002.f.(2)C. CA DATE 11-3-20.



PHOTO 10: ANOTHER IMAGE OF EROSION ON ROW SEE PHOTO 9 FOR CA.

Inspection Photos

Location Name: DIXIECUP 31-12 TR

API#: 05-071-08671

INSP. #: 695103045



Colorado Oil & Gas Conservation Commission
37.28001, -104.8351, 2242.0m, 240°
2020/08/03 14:47:34

**PHOTO 11: ANOTHER IMAGE OF EROSION ON ROW SEE
PHOTO 9 FOR CA.**