

Inspection Photos

Location Name: LAVIZ 12-7 FOLLOWUP

API#: 05-071-07540

INSP. #: 695103049



PHOTO 1: LOCATION

PHOTO 2: WELL SIGN

Inspection Photos

Location Name: LAVIZ 12-7 FOLLOWUP

API#: 05-071-07540

INSP. #: 695103049



PHOTO 3: PACKING ON WELLHEAD IS LEAKING. WILL CONTACT OPERATOR BY PHONE. **Control and contain spills/releases and clean up per Rule 906.a. CA DATE 8-4-20.**