

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type PIT

Comment: ADEQUATE

Corrective Action:

Date:

Equipment:

corrective date

Type: Prime Mover # 1

Comment: GAS ENGINE ON SKID DRIVING HYDRO PUMP.

Corrective Action:

Date:

Type: Progressive Cavity # 1

Comment:

Corrective Action:

Date:

Type: Deadman # & Marked # 5

Comment:

Corrective Action:

Date:

Type: Bradenhead # 1

Comment: IS PLUMBED TO SURFACE

Corrective Action:

Date:

Type: Vertical Separator # 1

Comment: INSIDE METER HOUSE

Corrective Action:

Date:

Type: Gas Meter Run # 1

Comment: CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.

Corrective Action:

Date:

Type: Ancillary equipment # 1

Comment: TELEMETRY EQUIPMENT

Corrective Action:

Date:

Type: Other # 3

Comment:	SOUND WALLS AROUND 3 SIDE OF ENGINE SKID.		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 262099 Type: WELL API Number: 071-07542 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Ditches	Pass	Culverts	Pass			
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
THIS IS A FOLLOWUP TO INSPECTION DOC#690200137. CA HAS BEEN ADDRESSED.	beardslt	08/03/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695103048	INSPECTION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5215927