

# Inspection Photos

API: 071-07186

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 8/3/2020



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-07186 | Date: 8/3/2020

## Inspection Photos



**Photo 1.** Facing west along the road near the location. Stormwater runoff from the location is directed down the road causing erosion. BMP's are needed in this area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07186 | Date: 8/3/2020



## Inspection Photos



**Photo 2.** Facing southwest toward the cut slope of the location. Stormwater runoff from this area is causing erosion shown in previous photo. BMP's are needed in this area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07186 | Date: 8/3/2020



## Inspection Photos



**Photo 3.** Facing northeast toward the fill slope. This area has been resloped and temporarily stabilized with straw blanket.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07186 | Date: 8/3/2020



## Inspection Photos



**Photo 4.** Facing southeast toward the area which was resloped and stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07186 | Date: 8/3/2020



## Inspection Photos



**Photo 5.** Facing northeast near the location. There is numerous Bull thistle noxious weeds in this area along the road. Also noticed noxious weeds at the base of the fill slope.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07186 | Date: 8/3/2020



## Inspection Photos



**Photo 6.** Further along the road there is an infestation of noxious weeds at Lat/Long:37.07427,-104.94714.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07186 | Date: 8/3/2020