

Inspection Photos

API: 071-06218

Operator: MERIDIAN OIL INC

Inspection Date: 8/3/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06218 | Date: 8/3/2020

Inspection Photos



Photo 1. Facing southwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06218 | Date: 8/3/2020

Inspection Photos



Photo 2. Facing south at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06218 | Date: 8/3/2020

Inspection Photos



Photo 3. Facing southeast at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06218 | Date: 8/3/2020

Inspection Photos



Photo 4. Facing east at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06218 | Date: 8/3/2020

Inspection Photos



Photo 5. Facing northeast at the location from the upper portion of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06218 | Date: 8/3/2020

Inspection Photos



Photo 6. There are BMP's that have filled in with sediment and need maintenance.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06218 | Date: 8/3/2020

Inspection Photos



Photo 7. Facing toward the reclaimed slope. Vegetation does not appear to be establishing in areas of the location. Additional reseeding may be needed during the fall season.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06218 | Date: 8/3/2020

Inspection Photos



Photo 8. Facing northwest. The filtrex wattles appear to be working well but will need maintenance.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06218 | Date: 8/3/2020