

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/22/2020

Submitted Date:

07/29/2020

Document Number:

695103003**FIELD INSPECTION FORM**Loc ID 306873 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10000

Name of Operator: BP AMERICA PRODUCTION COMPANY

Address: 1199 MAIN AVENUE SUITE 101

City: DURANGO State: CO Zip: 81301

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		SanJuanCOGCC@bp.com	All Inspections
Beebe, Sabre		sabre.beebe@bpx.com	All Inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
271492	WELL	PR	08/01/2018	GW	067-08931	LE PLATT B 1	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	PHOTO 3: Natural gas powered engine exhaust is staining soil/gravel around area of muffler. Remove stained soil/gravel and dispose. PHOTO 4: Approx 2' x 2' area of stained soil/gravel around base of wellhead. Clean-up and dispose of stained soil/gravel per Rule 1102.f.(2) and Rule 907.e.		
Corrective Action:	Comply with Rule 1102.f.(2) for best self inspection, maintenance and housekeeping to prevent breakdown or failure of BMP's. CA DATE IS ORIGINAL FROM PREVIOUS INSPECTION DOC#687904818		Date: 07/29/2020
Type	WEEDS		
Comment:	PHOTO 5: NOXIOUS WEEDS ON NORTH EDGE OF LOCATION NEAR GAS METER RUN FENCING.		
Corrective Action:	REMOVE NOXIOUS WEEDS COMPLY WITH RULE 1003.f.		Date: 07/29/2020

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	FENCE AROUND GAS METER RUN		
Corrective Action:			Date:
Type	PUMP JACK		
Comment:			
Corrective Action:			Date:

Equipment:

Type: Bradenhead	# 1		corrective date
Comment:	IS PLUMBED TO SURFACE		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.		
Corrective Action:			Date:

Venting:

Yes/No	NO		
--------	----	--	--

Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected Facilities				
Facility ID: <u>271492</u>	Type: <u>WELL</u>	API Number: <u>067-08931</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Producing Well				
Comment:				
Corrective Action:				Date: <div></div>

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
THIS IS A FOLLOW UP TO INSPECTION DOC# 687904818. THE CA FOR OILY RAGGS HAS BEEN ADDRESSED HOWEVER IT APPEARS THAT THE CA'S FOR IMPACTED SOILS AROUND WELLHEAD AND PUMPJACK MUFFLER HAVE NOT BEEN ADDRESSED. SEE HOUSEKEEPING FOR DETAILS ON THESE CA'S AND AN ADDITIONAL CA.	beardslt	07/22/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402455571	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5213045
695103004	INSPECTION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5213034