

FORM  
INSPRev  
X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/23/2020

Submitted Date:

07/29/2020

Document Number:

695103026

### FIELD INSPECTION FORM

Loc ID 326226 Inspector Name: Beardslee, Tom On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10133Name of Operator: HILCORP ENERGY COMPANYAddress: P O BOX 61229City: HOUSTON State: TX Zip: 77208**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**8 Number of Comments2 Number of Corrective Actions

- 
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Ray, Mandy	(505) 599-4083	mray@hilcorp.com	All Inspections
Roy, Catherine		catherine.roy@state.co.us	
Shorty, Priscilla		pshorty@hilcorp.com	All SW Inspections
Labowskie, Steve		steve.labowskie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216068	WELL	PR	10/14/1992	GW	067-07674	HUBER-LEWIS 2-4	PR

**General Comment:**

THIS IS A FIELD INSPECTION OF EQUIPMENT AND LOCATION ONLY. ALL CORRECTIVE ACTION FROM PREVIOUS INSPECTION DOC#693901253 THAT HAVE NOT BEEN ADDRESSED ARE STILL VALID AND NEED ADDRESSED.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER			
Comment:	PHOTO 4: AFTER NOTICING WHAT APPEARS TO BE USED OIL RUNNING DOWN CONCRETE PUMPJACK PAD I KICKED FRESH LAID DIRT ASIDE AND REVEALED AN AREA OF IMPACTED SOIL ON GROUND NEXT TO PUMPJACK ENGINE.			
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes. CA DATE 10-23-20.		Date:	10/23/2020
Type	WEEDS			
Comment:	PHOTO 3: MATURE FLOWERING NOXIOUS WEEDS ALL AROUND LOCATION AND ON INTERIM RECLAMATION AREA.			
Corrective Action:	Remove and properly dispose of weed debris.		Date:	01/20/2020

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	PUMP JACK			
Comment:	SOUND WALLS			
Corrective Action:			Date:	

**Equipment:**

Type		#		corrective date
Type: Bradenhead		# 1		
Comment:	IS PLUMBED TO SURFACE			
Corrective Action:			Date:	
Type: Gas Meter Run		# 1		
Comment:	CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.			
Corrective Action:			Date:	

**Venting:**

Yes/No	NO			
Comment:				
Corrective Action:			Date:	

**Flaring:**

Type				
Comment:				

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 216068 Type: WELL API Number: 067-07674 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402455633	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5213121">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5213121</a>
695103027	INSPECTION PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5213102">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5213102</a>