

FORM  
INSPRev  
X/15State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/28/2020

Submitted Date:

07/28/2020

Document Number:

699801520

## FIELD INSPECTION FORM

 Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
 312654 \_\_\_\_\_ De Paolo, Corey \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_
**Operator Information:**
 OGCC Operator Number: 53255  
 Name of Operator: MARALEX RESOURCES INC  
 Address: P O BOX 338  
 City: IGNACIO State: CO Zip: 81137
**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 7 Number of Comments  
 3 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
 PREVIOUS INSPECTIONS THAT HAVE NOT  
 BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, Engineering		dnr_cogccengineering@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
, BLM		jbyers@blm.gov	
Jordan, Reid		maralextechjr@gmail.com	
Graves, Jim		mrinc20@maralexinc.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222089	WELL	SI	05/01/2012	GW	077-08691	SULFUR GULCH 9-98-10 2	SI

**General Comment:****COGCC Inspection Report Summary**

On Tuesday 7/28/20 at approximately 11:00 hours, I, Inspector Corey De Paolo, Conducted a follow inspection at MARALEX RESOURCES INC SULFUR GULCH 9-98-10-69S98W /10NWNW, Location #312654 in Mesa County Colorado.

Refer to document #699800986 inspection conducted on 4/27/20. Not all corrective actions have been completed.

While there, I observed normal production operations.

During this inspection the following possible compliance issues were observed: Tank capacity, contents and NFPA labels weathered and not legible. See photo #1046 and #1631 with a previous corrective action date of 7/27/20. Multiple places with debris on location. See photo #1048, #1632, #1050 and #1633 with a previous corrective action date of 5/11/20. MIT required on well. With a previous corrective action date of 7/27/20.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Tank capacity, contents and NFPA labels weathered and not legible. See photo #1046 and #1631		
Corrective Action:	All tanks with a capacity of ten (10) barrels or greater shall be labeled with tank capacity, contents and NFPA labels. Properly label tank.	Date:	07/27/2020
<b>Emergency Contact Number:</b>			
Comment:	911		
Corrective Action:		Date:	
<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:	Multiple places with debris on location. See photo #1048, #1632, #1050 and #1633.		
Corrective Action:	Production facilities, shall be kept free of weeds and rubbish. Remove all debris from location.	Date:	05/11/2020
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	
<b>Equipment:</b>			
Type: Plunger Lift	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		

Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	OTHER	STEEL AST		
Comment:	Capacity and contents not labeled				
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 222089 Type: WELL API Number: 077-08691 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Well last produced October 2003. Last MIT preformed 9/19/14.

Corrective Action: A mechanical integrity test shall be performed on each shut-in well on 5 year intervals from the date the initial mechanical integrity test was performed. Preform MIT on well.

Date: 07/27/2020

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Berms	Pass			
		Ditches	Pass			
Ditches	Pass					
		Gravel	Pass			
Berms	Pass					

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402456105	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5213508">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5213508</a>
699801521	Photos for Insp. #699801520	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5213488">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5213488</a>